

Children's & Counseling Services 2000 South Summit Ave., Sioux Falls, SD (Business Occupancy)

1. The emergency exit from the boiler room would not open easily. The door would stick shut and would only open with a moderate amount of force.

Date of correction: 3-17-21

Plan of correction: Adjusted door strike and oiled handle assembly

Staff Position Responsible: Bill D. Now operating properly

2. The ninety-minute fire rated door into the boiler room would not latch with the self-closing device.

Date of correction: 3-17-21

Plan of correction: Adjusted the door closer and oiled door latching assembly.

Staff Position Responsible: Bill D. Now operating properly.

Community Support Services 100 W 5th St., Sioux Falls, SD (Business Occupancy)

1. The fire extinguishers had not been inspected monthly. (Life Safety Code 39.3.5 Extinguishment Requirements)

Date of correction: 3-17-21

Plan of correction: Just had Justice fire out and serviced extinguishers and had new tags put on. Will be checked, initiated and dated every month by maintenance

Staff Position Responsible: Jeff H.

2. In the kitchen the following items need to be corrected:

- a) The kitchen ceiling needs to be repaired. There are multiple holes in the sheet rock from previous water damage.

Date of correction: 3-30-21

Plan of correction: We re-sheetrocked and replanted damaged insulation in ceiling. All damaged areas have been fixed.

Staff Position Responsible: Bill D.

- b) The ventilation grates in the ceiling need to be cleaned.

Date of correction: 4-1-21

Plan of correction: cleaned and re-painted ceiling vents

Staff Position Responsible:

Jeff H.

210 North Main Ave. Suite 103, Parker, SD (Business Occupancy)

1. The fire extinguishers had not been inspected monthly.

Date of correction: 3-17-21

Plan of correction: Justice Fire just serviced extinguisher and put a new card on. Will be checked/dated and initialed monthly by maintenance

Staff Position Responsible:

Todd W.

121 North Main, Salem, SD (Business Occupancy)

1. The fire extinguishers had not been inspected monthly.

Date of correction: 3-17-21

Plan of correction: Justice Fire just serviced extinguishers and put a new card on. Will make sure they are checked, dated and initialed monthly by maintenance

Staff Position Responsible:

Todd W.

Agency Signature:

Trish J. Baham

Date:

4/8/2021